EPA-R5-2018-009810_0000157

Tradebe Treatment and Recycling LLC East Chicago, Indiana Permit Reviewer: Heath Hartley

Significant Permit Modification No. 089-34503-00345 Modified by: Heath Hartley Page 61 of 69 T089-29424-00345

INDIANA DEPARTMENT OF ENVIRONMENTAL MANAGEMENT OFFICE OF AIR QUALITY

COMPLIANCE AND ENFORCEMENT BRANCH PART 70 OPERATING PERMIT CERTIFICATION

Source Name:

Tradebe Treatment and Recycling LLC

Source Address:

4343 Kennedy Avenue, East Chicago, Indiana 46312

Part 70 Permit No.: T 089-29424-00345

RECTIVED
State of Indians

FEB 02 2016

Dest of Econocimental Appayances Office of Aut Challes

This certification shall be included when submitting monitoring, testing reports/results or other documents as required by this permit.				
Please check what document is being certified:				
Annual Compliance Certification Letter				
Test Result (specify)				
Report (specify) 2 throughput reports, Units 2r and 2s				
D Notification (specify)				
□ Affidavit (specify)				
Other (specify)				
I certify that, based on information and belief formed after reasonable inquiry, the statements and information in the document are true, accurate, and complete.				
Signature:				
Printed Name: Tita Lagrimas				
Title/Position: Executive VP of Regulatory Affairs				
Phone: 219.397.3951				
Date:				

Tradebe Treatment and Recycling LLC East Chicago, Indiana Permit Reviewer: Heath Hartley Significant Permit Modification No. 089-34503-00345 Modified by: Heath Hartley

Page 64 of 69 T089-29424-00345

INDIANA DEPARTMENT OF ENVIRONMENTAL MANAGEMENT OFFICE OF AIR QUALITY COMPLIANCE AND ENFORCEMENT BRANCH

Quarterly Report

Source Name:

Tradebe Treatment and Recycling LLC

Source Address:

4343 Kennedy Avenue, East Chicago, Indiana 46312

Part 70 Permit No.:

T 089-29424-00345

Facility:

Unit 2R

Parameter:

Liquid Material Throughput

Limit:

The throughput to Unit 2R shall be less than 41,450,000 gallons of liquid material per twelve (12) consecutive month period, each, with compliance determined at

the end of each month.

QUARTER: 4th

YEAR: 2015

Manth	Column 1 Column 2		Column 1 + Column 2		
Month	This Month	Previous 11 Months	12 Month Total		
October	545,136.	4,974,885.	5,520,021.		
November	458,055.	5,257,438.	5,715,493.		
December	614,702.	5,399,277.	6,013,979.		

No deviation occurred in this quarter. Deviation/s occurred in this quarter. Deviation has been reported on:	
Submitted by: Robert Vaughn	<u> </u>
Title / Position: EHS Manager	
Signature:	And the second s
Date: January 28, 2016	
Phone: 219.397.3951	

Tradebe Treatment and Recycling LLC East Chicago, Indiana Permit Reviewer: Heath Hartiey

Significant Permit Modification No. 089-34503-00345 Modified by: Heath Hartley

Page 65 of 69 T089-29424-00345

INDIANA DEPARTMENT OF ENVIRONMENTAL MANAGEMENT OFFICE OF AIR QUALITY COMPLIANCE AND ENFORCEMENT BRANCH

Quarterly Report

Source Name:

Tradebe Treatment and Recycling LLC

Source Address:

4343 Kennedy Avenue, East Chicago, Indiana 46312

Part 70 Permit No.:

T 089-29424-00345

Facility:

Unit 2S

Parameter. Limit

Liquid Material Throughput

The throughput to Unit 2S shall be less than 41,450,000 gallons of liquid material

per twelve (12) consecutive month period, each, with compliance determined at

the end of each month.

QUARTER:

4th

2015 YEAR:

Month	Column 1 . Column 2		Column 1 + Column 2		
MOUL	This Month	Previous 11 Months	12 Month Total		
October	1,617,771.	14,665,038.	16,282,809.		
November	1,342,392.	15,067,213.	16,409,605.		
December	1,387,409.	14,947,844.	16,335,253.		

No deviation occurred in this quarter. Deviation/s occurred in this quarter, Deviation has been reported on:
Submitted by: Robert Vaughn
Title / Position: EHS Manager
Signature:
Date: January 28, 2016
Phone: 219.397.3561

EPA-R5-2018-009810_0000157

Tradebe Treatment and Recycling LLC East Chicago, Indiana Permit Reviewer: Heath Hartley

Significant Permit Modification No. 089-34503-00345 Modified by: Heath Hartley

Page 61 of 69 T089-29424-00345

INDIANA DEPARTMENT OF ENVIRONMENTAL MANAGEMENT OFFICE OF AIR QUALITY COMPLIANCE AND ENFORCEMENT BRANCH PART 70 OPERATING PERMIT CERTIFICATION

Source Name:

Tradebe Treatment and Recycling LLC

Source Address:

4343 Kennedy Avenue, East Chicago, Indiana 46312

Part 70 Permit No.:

T 089-29424-00345

This certification shall be included when submitting monitoring, testing reports/results or other documents as required by this permit.
Please check what document is being certified:
Annual Compliance Certification Letter
□ Test Result (specify)
Report (specify) 2 quarterly reports VRU VOC Emissions, SDS and SDSII
□ Notification (specify)
Affidavit (specify)
Other (specify)
I certify that, based on information and belief formed after reasonable inquiry, the statements and information in the document are true, accurate, and complete.
Signature:
Printed Name: Tita Lagrimas
Title/Position: Executive VP of Regulatory Affairs
Phone: 219.397.3951
Date:

Tradebe Treatment and Recycling LLC East Chicago, Indiana Permit Reviewer: Heath Hartley

Significant Permit Modification No. 089-34503-00345 Modified by: Heath Hartley

Page 66 of 69 T089-29424-00345

INDIANA DEPARTMENT OF ENVIRONMENTAL MANAGEMENT OFFICE OF AIR QUALITY COMPLIANCE AND ENFORCEMENT BRANCH

Quarterly Report

Source Name:

Tradebe Treatment and Recycling LLC

Source Address:

4343 Kennedy Avenue, East Chicago, Indiana 46312

Part 70 Permit No.:

T 089-29424-00345

Facility:

Vapor Recovery Unit (VRU) associated with SDS

Parameter.

VOC emissions (after control)

Limit

VOC emissions (after control) from the Vapor Recovery Unit (VRU) shall not exceed 23.4 tons per twelve (12) consecutive month period, with compliance

determined at the end of each month.

Compliance with this limit shall be determined using the equation contained in

Condition D.1.10.

4th

QUARTER:

2015

Month	Golumn 1	Column 2	Column 1 + Column 2		
MOHUI	This Month	This Month Previous 11 Months			
October	2.366	18.645	21.011		
November	2.128	19.351	21.479		
December	1.640	19.486	21.126		

	No deviation occurred in this quarter. Deviation/s occurred in this quarter. Deviation has been reported on:
Submitte	ed by: Robert Vaughn
Title / Po	esition: EHS Manager
Signatur	
Date:	January 28, 2016
Phone:_	219.397.3951

Tradebe Treatment and Recycling LLC East Chicago, Indiana Permit Reviewer: Heath Hartley Significant Permit Modification No. 089-34503-00345 Modified by: Heath Hartley Page 67 of 69 T089-29424-00345

INDIANA DEPARTMENT OF ENVIRONMENTAL MANAGEMENT OFFICE OF AIR QUALITY COMPLIANCE AND ENFORCEMENT BRANCH

Quarterly Report

_	
Source	Virsus
ひいいし て	I VOLUME:

Tradebe Treatment and Recycling LLC

Source Address:

4343 Kennedy Avenue, East Chicago, Indiana 46312

Part 70 Permit No.:

T 089-29424-00345

Facility:

SDS II

Parameter:

VOC emissions (after control)

Limit.

VOC emissions after control from all the emission units associated with the SDS II shall be less than 95.6 tons of VOC per twelve (12) consecutive month period,

with compliance determined at the end of each month.

Compliance with this limit shall be determined using the equation contained in

Condition D.1.9.

QUARTER: 4

4th

YEAR: 2015

N d'an air ÉS.	Column 1	Colûmn 2	Column 1 + Column 2	
Month	This Month	Previous 11 Months	12 Month Total	
October	0.0	3.768	3.768	
November	0.390	3.768	4.159	
December	1.925	4.159	6.084	

No deviation occurred in this quarter. Deviation/s occurred in this quarter: Deviation has been reported on:
Submitted by: Robert Vaughn
Title / Position: EHS Manager
Signature:
Date: January 28, 2016
Phone: 219.397.3951

EPA-R5-2018-009810_0000157

Tradebe Treatment and Recycling, LLC East Chicago, Indiana Permit Reviewer: Heath Hartley Significant Permit Modification No. 089-34503-00345 Modified by: Heath Hartley

Page 69 of 69 T089-29424-00345

INDIANA DEPARTMENT OF ENVIRONMENTAL MANAGEMENT OFFICE OF AIR QUALITY COMPLIANCE AND ENFORCEMENT BRANCH PART 70 OPERATING PERMIT QUARTERLY DEVIATIONS AND COMPLIANCE MONITORING REPORT

Source Name:	Tradebe Treatme	ent and R	Recycling, LLC				
Source Address:	4343 Kennedy Av	venue, Ea	ast Chicago, Indiar	na 46312			
Part 70 Permit No.:	T 089-29424-003	45					
Months	: October	_ to	December		Year: <u>2</u>	015	
							Page 1 of 2
This report shall be subm							
Emergency Provisions sat	tisfies the reporting	g require	ments under para	igraph (a) c	of Section	C – General	Reporting.
Any deviation from the re	equirements of this	s permit,	the date(s) of eac	h deviation	n, the prol	bable cause	of the
deviation, and the respon							
applicable requirement t							
in the applicable requires							
necessary. If no deviatio							
period."		•					
□ NO DEVIATIONS	OCCURRED DURIN	IG THIS F	REPORTING PERIO	D			
× THE FOLLOWING	G DEVIATIONS OCC	URRED [DURING THIS REPO	ORTING PER	RIOD		
Permit Requirement (spe	ecify permit conditi	ion #)	A.2(a)(3)				
Date of Deviation:	October 1, 2015		Duration of Devi	iation:	32 days		
Number of Deviations: _	92	_					
Probable Cause of Devia	tion: <u>A.2(a)(3</u>) states r	orimary control is	for Tanks 6	/7 is flare	. The flare i	s not being
installed. Carbon caniste							
Response Steps Taken: _							ised to

reflect the actual VOC control being used on these storage tanks,

Tradebe Treatment and Recycling, LLC

Significant Permit Modification No. 089-34503-00345 Modified by: Heath Hartley

Page 69 of 69 T089-29424-00345

East Chicago, Indiana Permit Reviewer: Heath Hartley

Permit Requirement (specify permit condition #)			
Date of Deviation: October 1, 2015 Duration of Deviation: 92 days			
Number of Deviations: 92			
Probable Cause of Deviation: D.1.8 states testing on flare pursuant to 40 CFR 60.18 will be performed within			
180 days of issuance of the permit.			
Response Steps Taken: Verbal notification on 13 Oct 2015 and written notifications on 30 Oct 2015, 22 Dec			
2015, and 13 Jan 2016. Flare Performance Test conducted on 28 Jan 2016. Condition D.1.8 should be modified to			
require testing within 180 days after start-up of process unit SDS II to allow verification that Condition D.1.1(c) (i.e.			
Emission Offsets) is not an applicable requirement. Note that SDS II unit was shut down from 23 Aug 2015 to 24			
Nov 2015.			
Permit Requirement (specify permit condition #)			
Date of Deviation: October 23, 2015 Duration of Deviation: 54 days			
Number of Deviations: 54			
Probable Cause of Deviation: Container throughput limitation increased. Container throughput limitation			
into Unit 4 (Area 5) exceeded A.2.C. (1) maximum capacity of 27,365 pack containers per year. Please note these			
throughputs include containers that are not opened and/or processed in Booth1.			
December Chair Tuling Tilling Tilling			
Response Steps Taken: The amount of containers entering Unit 4: lab packing, depacking (an activity that does			
not include the opening of inner containers) and bulking operations, more commonly known as Area 5 Depack, for			
2015 has been identified as 35,394 containers. The containers processed can range in volume from small bottles			
(i.e., 100 milliliters) on up to 30-gallon container. Of the 35,394 containers entering Unit 4, over fifty (50) percent have been identified as containers that were not processed (i.e., poured off) in any of the four booths. Booths 2,			
3 and 4 are identified as insignificant activities.			
o and 1 die lacitation de decivities.			
The current permit identifies the capacity of Unit 4 as 27,375. This topic was briefly discussed during the booth 1			
stack testing and Tradebe would like to discuss this with the IDEM prior to submittal of a modification request to			
revise Condition A.2(c) to reflect a volume or mass associated with Unit 4 activities.			
Paramete Parameter and Co. 16 To the U.S. The Co. 10 To the U.S. The U.S. The Co. 10 To the U.S. T			
Permit Requirement (specify permit condition #)			
Date of Deviation: December 18, 2015 Duration of Deviation: 2 Days			
Number of Deviations:2			
Probable Cause of Deviation: Blower for Tank 24 HP feed hopper carbon control system was not operating			
while processing hazardous waste material.			
Response Steps Taken: On January 26, 2016 the operation blower for the Tank 24 HP feed hopper carbon			
control system was interlocked to the hydraulic system for processing material through the hopper so it is not			
possible to operate the hydraulic system without the blower being on. This will prevent future occurrences of this			
deviation.			

Tradebe Treatment and Recycling, LLC East Chicago, Indiana Permit Reviewer: Heath Hartley Significant Permit Modification No. 089-34503-00345 Modified by: Heath Hartley

Page 69 of 69 T089-29424-00345

Permit Requirement (specify permit condition #)		
Date of Deviation:	Duration of Deviation:	
Number of Deviations:		
Probable Cause of Deviation:		
	A my	
Signature:		
Form Completed by:	Tita LaGrimas	
Title/Position:	Executive VP of Regulatory Affairs	
Date:	January 29, 2016	
Phone:	219-397-3951	

UPS Next Day Air® UPS Worldwide Express**

UPS 2nd Day Air®


Visit ups.com® or call 1-800-PICK-UPS® (1-800-742-5877) to schedule a pickup or find a drop off location near you.

Domestic Shipments

To qualify for the low correspondence weigh 8 pz. or lithose listed or v

- International Sal The UPS Express value, Certain of ups.com/impos
- To qualify for the UPS Express End

Note: Express Eav containing secsion or cash equivalent



https://www.campusship.ups.com/cship/create?ActionOriginPair=default___PrintWindow... 1/29/2016

Serving you for more than 100 years United Parcel Service.





010195101 4/14 PAC United Parcel Service